

3D Printing Trunk Supply List

Materials	Quantity	Uses/Special Info
Printrbot 3D Printers	4	Prints STL files in three dimensions.
Thinkpad Laptops	4	For designing and uploading STL files.
Laptop Chargers	4	Delivers power supply to laptops.
Orange Extension Cord	1	Power supply; should be always plugged in.
Power Strips	2	One located on each level of the trunk.
USB Cables	4	Connects laptops to 3D printers.
Extra Printer Filament Rolls	Will vary	Gets heated by printer and turned into your product!
Bamboo Sticks	1 pack	For unsticking product once finished printing.
Blue Printer Tape	1 roll	Should completely cover surface of the printing bed.
Ruler	1	For measuring product/printer bed.
Scissors	1	For sculpting product and cutting filament.
Xacto Knife	1	For scraping filament off of bed.
Metal Spatula	1	For scraping filament off of bed/unsticking product.
Flathead Screwdriver	1	For scraping filament off of bed
Needle Nose Pliers	1	For sculpting printed product (shaving off excess filament).
Wire Cutters	1	For sculpting printed product (shaving off excess filament).
Calibration Spacer	1	For calibrating Z value of printers.
Spare 3D Printer Parts	Will vary	For replacing broken 3D printer parts.